

VEHICLE INSPECTION REPORT

VN16PKC

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	20/06/2016	Colour	WHITE	Gearbox	AUTOMATIC
Year	2016	VIN	SEG2628HR6BG22448	Axle Combi	6x2
Mileage	107,965 Km Warranted	Body Style	Refuse Collector	Steering Combi	Rear Steer
Fuel Type	Diesel	Cab Type	CREW CAB	Rear Suspension	Air

OLYMPUS BODY, TERBERG SPLIT LIFT, SURROUND CAMERA SYSTEM

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cloth seat trim
- Park assist camera
- Radio/CD
- Front electric windows

Photos





Condition Check



Damage Photos



1: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint



2: Screen Front
Chipped
UpTo 10mm



3: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		