



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE17HMJ

Daf CF 440

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	01/03/2017	Colour	RED	Gearbox	AUTOMATIC
Year	2017	VIN	XLRTGM4100G148542	Axle Combi	6x2
Mileage	972,848 Km Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Cab Type	SLEEPER CAB	Rear Suspension	Air

COLLECTED AS NON-RUNNER, AIR TANK, BRAKE HOSES, TYRES & FLOOR REQUIRE ATTENTION



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Moulding
Broken
Replace

4: Door osf
Dented
With Paint Damage



5: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

OK
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		