

VEHICLE INSPECTION REPORT

YT68EDV

MERCEDES-BENZ ACTROS 1824

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	29/10/2018	VIN	WDB96300320272318	Gearbox	AUTOMATIC
Year	2018	Body Style	Box Van	Axle Combi	4x2
Mileage	353,601 Km Warranted	Service history	Yes	Rear Suspension	Air
Fuel Type	Diesel	Service documents	Printout	Rear Doors	Roller
Colour	WHITE	Cab Type	SLEEPER CAB	Tail Lift	Column

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Radio/CD

Photos



