

VEHICLE INSPECTION REPORT

MA56287

KRONE CURTAINSIDE MEGA EUROLINER

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2015	Colour	BLUE	Axle Combi	Tri
Year	2015	VIN	WKESD000000682208	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

NOT REGISTERED IN THE UK BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS, SLIDING ROOF, ENXL RATED

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





